

1995 Bell 206BIII Corporate Configured



GENERAL

Serial Number: 4386 Registration: H-41 Airframe TT: 4999.0 Engine TT: 3715.1 Cycles: 2489 Passenger/Corporate Configuration Located: Royse City, Texas

EQUIPMENT

Dual Controls Particle Separator Freon Air Conditioning w/Dual Forward Evaporators Passenger Wedge Windows AAI Wire Strike Protection System AAI Maintenance Step and Pre-flight Step/Handle AAI Door Openers AAI Cockpit Floor Protectors AAI Baggage Spacemaker High Skid Gear w/Flite Steps (To Be Installed)

Component Remaining Value: 62.1% Fresh Annual Inspection at Delivery All Mandatory Bulletins Current Status at Delivery

INTERIOR/EXTERIOR

5-Place Tan Leather Interior w/Brown Carpet Base White w/Green, Yellow and Black Accent Stripes

AVIONICS

NAT AMS-44 Dual Channel Audio Controller Garmin G-500H TXi 7" Display Garmin GTN-650 Nav/Com/GPS Garmin GTX-33 Transponder (remote) Honeywell KY-196A Com Honeywell KN-63 DME Davtron Digital Clock

MISCELLANEOUS

No damage history All Records/Tie Downs and Covers Included

CONTACT

Fred Wagner214-679-7291fred@hmahelicopters.comScott Wagner724-309-5060scott@hmahelicopters.com

¢ 775 (

\$725,000 FOB Royse City, Texas

Email: <u>sales@hmahelicopters.com</u> Website: <u>www.hmahelicopters.com</u> Specifications subject to verification upon inspection. Price and times subject to change without notice. Aircraft offered subject to prior sale or withdrawal from market.

PRICE

Phone: 817-354-0400 Fax: 817-354-0402 27 September 2023



1995 Bell 206Bill Corporate Equipped

AIRCRAFT COMPONENT STATUS

Aircraft Model:	Bell 206BIII	Annual Inspection Due:	TBD
Serial Number:	4386	Total Airframe Hours:	4999.0
Engine:	RR250-C20J	Total Engine Hours:	3715.1
Engine Serial:	CAE-834077	Total Cycles:	2489

Retirement Items Time Remaining

Main Rotor Blade	2805.6
Main Rotor Blade	2805.6
Main Rotor Grip	4360.1
Main Rotor Grip	4360.1
Main Rotor Trunnion	4360.1
Main Rotor TT Strap x 2 (Hrs)	1200.0
Main Rotor TT Strap x 2 (Cal)	48 Months
Main Rotor Latch Bolt	2060.1
Main Rotor Latch Bolt	2060.1
Main Rotor Fitting	1960.1
Main Rotor Fitting	1960.1
Main Rotor Pin	2060.1
Main Rotor Pin	2060.1
Swashplate Sleeve	13960.1
Swashplate Support	4360.1
Collective Lever	4360.1
Collective Idler Link	4360.1
Lower Collective Tube	4360.1
Freewheel Clutch	2560.1
Tail Rotor Blade	1411.8
Tail Rotor Blade	1411.8
Tail Rotor Yoke	4560.1
Hydraulic Support	5001.0
Tail Rotor Gearbox Bearing	2560.1
Starter Generator Overhaul	999.1

Overhaul Items Time Remaining

Freewheel Assembly	2560.1			
Main Driveshaft	600.0			
Hydraulic Servo Actuator	2175.0			
Hydraulic Servo Actuator	1201.0			
Hydraulic Servo Actuator	2175.0			
Hydraulic Pump	3687.0			
Main Rotor Hub Assembly	1960.1			
Main Rotor Mast Assembly	2558.1			
Transmission Assembly	3975.7			
Swashplate Assembly	4360.1			
Tail Rotor Gearbox Assembly	5560.1			
Tail Rotor Hub Assembly	2060.1			
Engine Items Time Remaining				

Compressor	2080.5
Impeller	2110.6
Turbine Hot Section	792.8
1st Stage Turbine Wheel (Hrs)	839.3
2nd Stage Turbine Wheel (Hrs)	839.3
3rd Stage Turbine Wheel (Hrs)	1842.8
4th Stage Turbine Wheel (Hrs)	1842.8
Governor Overhaul	1573.0
Fuel Nozzle Overhaul	2157.0
Fuel Pump Overhaul	1610.8
Fuel Control Overhaul	2412.6
Bleed Valve Overhaul	1073.0

Email: <u>sales@hmahelicopters.com</u> Website: <u>www.hmahelicopters.com</u> Specifications subject to verification upon inspection. Price and times subject to change without notice. Aircraft offered subject to prior sale or withdrawal from market. Phone: 817-354-0400 Fax: 817-354-0402 27 September 2023